

Machine tools are dangerous and may cause great injury. This information was collected from a variety of sources, is neither complete nor verified, and is of a general nature for theoretical study only. Any attempt to duplicate the operations described should be done with the guidance and supervision of a qualified instructor who will teach the appropriate safety skills and fill in the missing details. Follow this link for [Statements of Warning, Limitation & Responsibility.](#)



## Cutting Speed & Feed Rates

You should calculate RPM & Feed whenever machining with a Mill, Drill or Lathe. Experienced machinists often "fudge it" while manual machining, making changes based on the "feel" of the machine and the sound of the cut. With CNC the RPM & Feeds need to be right before you hit the green button.

[Definitions & Explanations](#)  
[Cutting Speeds and Lathe Feed](#)  
[Milling Machine Feed Rates](#)  
[My Tests with Plastic](#)

[Quick RPM Table](#)  
[Calculating RPM](#)  
[Calculating Feed](#)  
[Speed and Feed Links](#)

**Cutting Speed(CS)** of a material is the ideal number of Feet-per-Minute that the tool-bit should pass over the work-piece. This "Ideal" cutting speed assumes sharp tools and flood coolant. Adjustments need to be made for less than ideal cutting conditions. Different materials (High-Carbon/Low-Carbon Steels, Aluminums, Different kinds of Plastics) have different Cutting Speeds and can be worked/cut at different rates. In addition, some tools or processes (like threading, knurling, or cutting-off) will need to be worked at slower speeds than the Cutting Speed would indicate.



**Feed Rate(Milling Machine)** refers to how fast a milling-tool moves through the material being cut. This is calculated using the **Feed Per Tooth(FPT)** to come up with the **Inches Per Minute** that a milling bit can move through a particular type of material. Thus, a Four-Flute End-Mill will cut through material at twice the speed of a Two-Flute End Mill. Feed Rates will decrease with dull tools, a lack of coolant, or deep cuts.

**Feed Rate(Lathe)** refers to how fast a lathe-tool should move through the material being cut. This is calculated using the **Feed Per Revolution** for the particular material. Lathe tools generally have only one tooth, so in most cases the FPT and FPR will be the same. Feed rates will decrease with dull tools, a lack of coolant/lubrication, or deeper cuts.

**Diameter** refers to the diameter of whatever is spinning: work-piece(Lathe) or cutting tool-bit(Mill/Drill). *\*As the diameter gets bigger use a slower RPM.*

**RPM(Revolutions Per-Minute)** is the turning speed of whatever is spinning: On a Lathe this is the work-piece. On a Mill or a Drill it is the cutting-tool. *\*Using Cutting Speed and Diameter you can calculate RPM as shown further down on this page.*

When calculating spindle speed(RPM), round down to the slower speed option offered by your Lathe/Milling Machine/Drill. Operations like Threading, Knurling, or Parting-off, require much slower speeds (Generally 1/3 to 1/4 Calculated RPM for Threading, Knurling & Parting-off).

### Approximate Material Cutting Speeds & Lathe Feed-Per-Revolution: Calculating RPM and Feed Rates

Material	Ballpark CS with High-Speed Tool	Cutting Speed High-Speed Tool	Cutting Speed Carbide Tool	Feed/Rev HSS Tool Lathe*	Feed/Rev Carbide Tool Lathe*
SAE 1020 - Low Carbon Steel	100	80-120	300-400	.002-.020	.006-.035
SAE 1050 - High Carbon Steel	60	60-100	200	.002-.015	.006-.030
Stainless Steel	100	100-120	240-300	.002-.005	.003-.006
Aluminum	250	400-700	800-1000	.003-.030	.008-.045
Brass & Bronze	200	110-300	600-1000	.003-.025	.008-.040
Plastics*	250	200- 500	1000	.005-.050	.005-.050

*\*Variation in Cutting-Speed & Feed-per-Revolution will exist with different alloys, procedures, tools & desired finishes. Feed-Per-Revolution is also affected by the size of the lathe-tool, as well as the depth of cut. The cutting speed and speed of plastics will vary greatly depending upon the type of plastic.*

**Link: [Cutting Speeds by Specific Alloy](#)**

### Approximate Feed Rates (Feed Per Tooth) for End Mills

Material	.050" Depth of Cut	.250" Depth of Cut

	1/8"	3/8"	1/2"	3/8"	3/4"
<b>Plain Carbon Steels</b>	.0005-.001	.002-.003	.003-.004	.001-.002	.002-.004
<b>High Carbon Steel</b>	.0003-.001	.001-.003	.002-.004	.0003-.001	.001-.004
<b>Tool Steel</b>	.0005-.001	.001-.003	.002-.004	.001-.002	.003-.004
<b>Cast Aluminum Alloy</b>	.002	.003	.005	.003	.008
<b>Cast Aluminum -Hard</b>	.001	.003	.005	.003	.006
<b>Brasses &amp; Bronzes</b>	.0005-.001	.003-.004	.004-.006	.002-.003	.004-.006
<b>Plastics</b> *Much Variation	.002	.004	.005	.003	.008

\*Variation in Feed-per-Tooth exists with different Material Alloy Harness, Tool Qualities, Cutting Techniques and Desired Finishes. Contact the manufacturer if precision is important.

### Twist Drill Feeds (Feed per Revolution)

Drill Size Inches	Drill Feed Inches	Drill Size Metric	Drill Feed Millimeter
1/8" and smaller	0.001" to 0.002	3mm and smaller	.02mm to 0.05mm
1/8" to 1/4"	0.002" to 0.004"	3mm to 6mm	0.05mm to 0.10mm
1/4" to 1/2"	0.004" to 0.007"	6mm to 13mm	0.05mm to 0.10mm
1/2" to 1"	0.007" to 0.015"	13mm to 25mm	0.18mm to 0.38mm
1 to 1 1/2"	0.015 to 0.025"	25mm to 38mm	0.38mm to 0.63mm

### Quick RPM/Spindle Rate Calculations: Lathe, Mill, Drill (HSS Cutter)

(RPM changes with Cutting Speed & Diameter)

Material	1/4" Dia	1/2" Dia	1" Dia	1 1/2" Dia	2" Dia
<b>Low-Carbon Steel</b>	1600 RPM	800 RPM	400 RPM	267 RPM	200 RPM
<b>High-Carbon Steel</b>	960	480	240	160	120
<b>Aluminum</b>	4000	2000	1000	667	500
<b>Brass &amp; Bronze</b>	3200	1600	800	533	400

\* RPM Spindle Speed Examples calculated using Ballpark Cutting Speeds with High-Speed Steel cutting tools

### Calculating RPM

#### Lathes, Milling Machines, Drills

RPM (Turning Spindle Speed) of the cutting tool or work piece is calculated as follows:

$$RPM = (Cutting\ Speed \times 4) / Diameter$$

**RPM = Spindle Speed**

**Cutting Speed = Cutting Speed for the material being cut/worked.**

**Diameter = The Diameter of whatever is turning.**


**Example #1** Calculate RPM for turning a 1 inch diameter piece of Low-Carbon Steel with a Cutting Speed of 100 on a Lathe. (Double-check CS table)

$$RPM = (100 \times 4) / 1 = 400\ RPM$$

**Example #2** Calculate RPM (Spindle Speed) for a 1/2 inch High-Speed-Steel 2 Flute End-Mill cutting Aluminum with a CS of 250 on a Milling Machine

$$RPM = (250 \times 4) / .5 = 2000\ RPM$$

### Calculating Feed Rates



[Link: Machine Shop Feed Rates Explained](#)

#### Milling & Drilling

The Feed Rate in "INCHES Per MINUTE" is determined by multiplying the number of cutting teeth by the RPM, multiplying that product by the Feed per Tooth, and dividing by 3. The calculation is as follows:



**Feed Rate = (Number of Cutting Teeth x RPM x Feed Per Tooth)**

**Example #3** Use the information and RPM calculated in Example #2 for a Milling Machine, ball-parking the FPT(Feed per Tooth) of .005 (see table), and a cutting depth of .050"

$$Feed\ Rate = (2 \times 2000 \times .005) = 20\ inches/minute$$

#### Lathes

On lathes the Feed is generally



expressed as Feed per Revolution. In practical terms this is easy. Input the Feed per Revolution for basic turning. As the RPM changes, so too will the movement of your lathe bit.

FACE	DEPTH OF CUT	7	8.5	8	5.75	5.5	5	4.5	4
-10.3190 in	0.0250 in	059	064	069	072	075	083	092	104
FACE	DEPTH OF CUT	14	13	12	11.5	11	10	9	8
-25.2646 in	0.0288 in	0295	032	0345	036	0375	0415	046	052
INSIDE DIA	<b>FEED PER REV</b>	28	26	24	23	22	20	18	16
1.1250	<b>0.0060 in</b>	0147	016	0172	018	0187	0207	023	026
A. TO CUT	SPINDLE RPM	56	52	48	46	44	40	36	32
-0.0320 in	1000	0073	008	0086	009	0098	0103	0115	013
		112	104	96	92	88	80	72	64
		0036	004	0043	0045	0046	0051	0057	0066
		224	208	192	184	176	160	144	128
		0018	002	0021	0022	0023	0025	0028	0032

### Plastic on a CNC Lathe... a greenhorn's perspective

The following, with stock held in a 3-Jaw Chuck and using a sharp HSS lathe tool, worked for me. Your results may differ:

<b>Acetal/Delrin</b> - Turning at CS 325, Depth of Cut 0.035, Feed 0.015 - 0.010	Depth of Cut could be increased. Slower Feed Rate gives smoother finish. At 0.015 Feed Rate there were striations.
<b>UMHW</b> - Turning at CS 450, Feed 0.015	Nice finish. Slower speeds produced a rougher finish.
<b>UMHW</b> - Part-Off at CS 250, Feed 0.01	Parted smoothly.

When turning plastic, taking too aggressive a cut can cause the plastic to deform and pull from a 3-Jaw chuck. This has happened to me. Also, I generally use lower-speeds and higher-feeds when drilling plastic, as heat builds up and begins to melt the inside of the hole.

### [Quick RPM Spindle Rate Table](#)

#### Speed and Feed Links

[Fox Valley Tech Feeds & Speeds](#)

[Link - Suggested Cutting Speeds](#)

[Link - More Cutting Speed Charts](#)

[Link - Pierce College Cutting Speed & Feed](#)



[Top of Page](#)

copyright 2009



